Q-322

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

QVM BULLETIN: Q-322 DATE: 05 / AUG / 2020

MODEM AND ANTENNA LOCATIONS FOR E-SERIES AND MEDIUM DUTY

REVISION	UPDATE	REVISION DATE
Q-322	INITIAL RELEASE	05 / AUG / 2020

MODEL(S) AFFECTED:
2021MY+ MEDIUM DUTY AND E-SERIES (NOT APPLICABLE TO E-SERIES STRIP CHASSIS)

ISSUE / DESCRIPTION:
Purpose of this Bulletin is to communicate the locations of the Modem and Antenna for the affected vehicles. This should have no impact to second unit body upfits and no external Antenna requirements needed.

E-SERIES



PIFA = Planar Inverted-F Antenna

MEDIUM DUTY



PIFA = Planar Inverted-F Antenna

Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the Ford Body Builders Advisory Service as shown in the header of this bulletin.